

Replacement Heater Control Valves









BV Series Replacement Heater Control Valves by Klima Design Works (patent pending) are designed to replace specific Bosch "monovalve" and "duovalve" heater control valves found in a range of 1980s-1990s Mercedes, BMW E24 and E28 Series, Bentley, Ferrari, and 1990s Volkswagen T4 EuroVans.

BV Series heater control valves offer:

- **Drop-in fit.** Mount up to original brackets, hoses, and electrical connections.
- **Reliable operation**. Reliable at high engine RPMs, and extreme temps.
- Longevity. Provides years of like-new performance with field-rebuildable internals.

BV Series valves are available for:

Mercedes W123 models with automatic climate Control III, MY 1981-198 (240D, 280CE, 300D, 300CD, 300TD & others). See chart below for details.

Mercedes R107 models with Automatic Climate Control III, MY 1981-1989 (380SL, 560SL & Others). See chart below for details.

Mercedes W126 models with Automatic Climate Control III, MY 1980-1991 (numerous models). Single and dual zone versions available. See chart below for details.

BMW E24 and E28 Models with Mono Valve, MY 1982-1988. See chart below for details.

Ferrari models 456, F40, F50, Mondial, Testarossa, & others. See OE data for P/N 61079000.

Volkswagen EuroVan T4 Models MY 1990-1999. See chart below for details.

Compatibility Information:

BV / Klima Part Number	Replaces OE Part Number	Vehicle List (Partial)	OE Part Image
BV-1.0 Mercedes W123 models	MB A 000 830 29 84 I MB A0008302984 I MB 0008302984	240D 1981-83 I 280CE 1981-81 I 280E 1981-81 I 300CD 1981-85 I 300D 1981-85 I 300TD 1981-85	
BV-1.5 Mercedes W123 w/ CA Emissions		300CD 1985 I 300D 1985 I 300TD 1985	
BV-2.0 Mercedes R107 models	MB A 000 830 34 84 I MB A0008303484 I MB 0008303484	560SL 1986-89 I 380SL 1980-1985	
BV-3.0 Mercedes W126 models with 3-barb housing (w/o heated windshield washer)	MB A 000 830 18 84 I MB A0008301884 I MB 0008301884	By part number cross reference. Euro and other models.	
BV-4.0 Mercedes W126 models with 4-barb housing (w/ heated windshield washer reservoir)	MB A 000 830 37 84 I MB A0008303784 I MB 0008303784	300SD 1981-85 I 300SDL 1986-87 I 300SE 1988-91 I 300SEL 1988-91 I 350SD 1991-91 I 350SDL 1990-91 I 380SE 1984-85 I 380SEC 1982-83 I 380SEL 1981-83 I 420SEL 1986-91 I 500SEC 1984-85 I 500SEC 1984-85 I 560SEC 1986-91 I 560SEL 1986-91 I	

BV / Klima Part	Replaces OE Part	Vehicle List	OE Part Image
BV-5.0 BMW E24 E28 models with vertical output barb I VW Eurovan T4	Number BMW 64111373191 I VW 701963375	(Partial) E28 528e 1982-1988 I E28 524td 1985-86 I E28 533i 1983-84 I E28 535i 1985-88 I E28 M5 1988 I E24 633CSi 1980-82 I E24 635CSi 1985- 88I E24 M6 1987 I VW EuroVan T4 Models 1990-1999	
BV-6.0 BMW E28 Models with horizontal output barb. Ferrari	BMW 64111373188 Ferrari 61079000	E28 528e 1982-1988 I E28 524td 1985-86 Ferrari: Use OE cross-reference for applicable models.	
BV-7.0 Mercedes W126 models with 3-barb housing duo valve (w/o heated windshield washer reservoir)	MB A 126 830 00 84 I MB A1268300084 I MB 1268300084	By part number cross reference. Euro and other models.	
BV-8.0 Mercedes W126 Models with 4-barb housing duo valve (with heated windshield washer)	MB A 000 830 38 84 I MB A0008303884 I MB 0008303884	By part number cross reference. Euro and other models.	
REPAIR KITS In some additional applications where Bosch / Behr Mono Valve Repair Kit is called for.	MB 000 835 06 44 I A0008350644 I 0008350644 I Bosch 1147213007 I BMW 64118390132	By part number cross reference. Replacement not available for BMW E32 Duo Valve 64111388619.	N/A